



Item no: 3101602

### Vacuum gauge 100 -kPa, with nut / -30 inHg

- Analogue indicator, springjoint – lever system
- The instruments include nut for installation on a panel

General

Material	ABS, PMMA, CUZN
Medium	Vacuum
Weight	90 g

Electrical data

Accuracy, electrical	2,5 % FS
----------------------	----------

Signal function"

Signal range	0 - 100 -kPa
--------------	--------------

Dimensional drawings 

